










Dates	Nom du visiteur	Signature	Observations
5.4.71	Bourinot inf		Câble à remplacer
6.5.71	- id° -		Câble à remplacer
8.5.71			Dépose du vieux câble du contrepoids - remplacé par un câble neuf - (mêmes caractéristiques) -
3.6.71	- id° -		Rien à signaler.
19.7.71	- id° -		- id° -
2.9.71	- id° -		- id° -
7.10.71	- id° -		- id° -
19.11.71	- id° -		- id° -
17.12.71	- id° -		- id° -
26.01.72	- id° -		- id° -
18.02.72	- id° -		- id° -
24.03.72	- id° -		Supprimer la partie usagée
4 ou 5 Avril 72			Coupage du câble contrepoids afin d'éliminer la zone usagée -